



Fred Gerber Deputy Director, Enfield Public Works Re: Mold and Indoor Air Quality Results Enfield High School December 6, 2023

On September 18-22, 2023, EnviroMed Services conducted a Baseline Mold and Indoor Air Quality Assessment at Enfield High School. The initial findings revealed elevated levels of airborne Cladosporium mold spores in the E Wing Automotive Classroom. Cladosporium is a typical airborne allergen commonly detected in ambient air samples. Elevations of common allergens like Cladosporium are not unusual during periods of higher humidity or moisture levels.

Following these findings, the E Wing Automotive Classroom was cleaned and disinfected thoroughly to eliminate any elevations of airborne mold. On November 7, 2023, EnviroMed Services conducted Clearance Air Testing in the E Wing Automotive Classroom to confirm the successful remediation of the airborne elevation. This air test revealed no elevations of Cladosporium or any other airborne mold. EnviroMed Services considers this Test a PASS and considers the space safe for student use.



Cleaner environment. Safer workplaces.

Baseline Indoor Air Quality Report For

Enfield High School 1264 Enfield Street Enfield, CT 06082

Prepared For

Russell and Dawson 1111 Main Street East Hartford, CT 06108

Dates of Inspection and Testing:

September 18 – September 22, 2023, and November 7, 2023

Revision Date:

December 5, 2023

EnviroMed Project # IH-23-1377

EnviroMed Services, Inc. 470 Murdock Ave., Meriden, CT 06450 Telephone (203) 238-4846• Facsimile (203) 238-4243

TABLE OF CONTENTS

| | Section | Page |
|----|--------------------------------------|------|
| I. | PROJECT NARRATIVE | 1 |
| | Overview | |
| | Methods | 1 |
| | Summary of Results | |
| | Conclusions | 13 |
| | Recommendations | |
| | I. TABLE OF IAQ MEASUREMENTS | |
| | II. PHOTOGRAPHS | |
| | V. LABORATORY ANALYSIS REPORT | |
| | LABORATORY ANALYSIS CLEARANCE REPORT | |
| | I. LABORATORY CERTIFICATION | |
| V | I. LADURATURI CERTIFICATION | |

I. PROJECT NARRATIVE

Overview

From September 18 to September 22, 2023, and November 7, 2023, EnviroMed Services conducted a microbial and indoor air quality assessment for Enfield High School, located at 1264 Enfield Street, Enfield, Connecticut. The purpose of this assessment, as directed by Russell and Dawson Architects & Engineers (the Client), was to measure indoor air quality and baseline survey of high occupancy areas for airborne fungal contamination.

Methods

The following sampling and assessment scheme was employed:

- Direct reading measurements were collected using a TSI Q-TrakTM model 8550/8551 IAQ Monitor. The baseline indoor air quality (IAQ) parameters temperature (°F), relative humidity (%), carbon monoxide (ppm), and carbon dioxide (ppm).
- Direct reading measurements for Volatile Organic Compounds (VOCs) were taken using a ppb RAE 3000 Photo Ionization Detector (PID).
- Direct reading measurements were taken for total particulates in the air using an MIE PDR 1000 Personal Data Ram Particle Analyzer.
- Direct reading measurements for Formaldehyde were taken using a Single Gas Forensics Detector.
- Conduct air sampling to measure the presence of airborne fungal structures, including spores, by drawing air through a Zefon Air-O-Cell cassette using a pre-calibrated vacuum pump. In this method, air enters the cassette and particles are collected on the sampling substrate. The manufacturer-recommended flow rate of 15 liters per minute of air, for a duration of 10 minutes, was used to collect each sample. Sample locations were selected based on client direction. A total of 13 samples were sent to Hayes Microbial Consulting in Midlothian, VA, for analysis by optical microscopy. Hayes Microbial Consulting is approved by the American Industrial Hygiene Association (188863) and the state of Connecticut Department of Public Health. The results are represented in counts of fungal structures and fungal structures per cubic meter of air (spores/m³).

Summary of Results

Indoor Air Quality Results

Indoor Air Quality Parameters:

Temperature: The ASHRAE recommended temperatures range from 72.0 to 80.0 °F (for Summer Months).

Relative Humidity: The ASHRAE recommended range for indoor relative humidity is 20 to 60 percent.

Carbon Monoxide: The OSHA PEL limit for carbon monoxide is 50 ppm, reported as an 8-hour time-weighted average.

Carbon Dioxide: Per the ASHRAE Standard 62-2001, Ventilation for Acceptable Indoor Air Quality, the difference between the indoor and outdoor concentrations should be less than 707 ppm. Additionally, the OSHA permissible exposure limit for carbon dioxide is 5000 ppm.

Particulates in Air (Dust): The OSHA Permissible Exposure Limit (PEL) for respirable and total particulates is 5 mg/m3 and 15 mg/m3 respectively.

Volatile Organic Compounds (VOCs): The maximum concentration of Total VOCs per the Leadership in Energy and Environmental Design (LEED) Standards is 0.5 ppm.

Formaldehyde (CH_2O): The OSHA formaldehyde limit is 0.75 ppm, reported as an 8-hour time weighted average.

IAQ Readings - September 18, 2023

Temperature: The indoor temperatures ranged from 66.5 to 74.8 °F. The indoor temperatures were below the ASHRAE recommended range.

Relative Humidity: The indoor relative humidity ranged from 55.2 to 81.5 percent. Some of the relative humidity readings were above the ASHRAE recommended range of 20 to 60 percent relative humidity.

Carbon Monoxide: Indoor carbon monoxide concentrations ranged from ppm 0.7 to 1.2 ppm. These concentrations are below the OSHA PEL limit.

Carbon Dioxide: The outside carbon dioxide concentration recorded on this day was 558 ppm. The indoor concentrations ranged from 605 to 1344 ppm. The difference between the highest indoor concentration and the outdoor concentration was 786 ppm. This is slightly above the recommended difference of less than 707 ppm. Additionally, carbon dioxide concentrations were well below the OSHA permissible exposure limit.

Particulates in Air (Dust): The indoor concentration of particulates in air inside the building did not exceed 0.013 mg/m3. The concentration of particulates in air inside the building was well below the OSHA PEL at the time of the assessment.

Volatile Organic Compounds (VOCs): VOC readings ranged from 0.0 to 0.375 which is below the standard of 0.5 ppm.

Formaldehyde: Formaldehyde levels did not exceed 0.00 ppm throughout the testing. This concentration is below the OSHA formaldehyde limit.

IAQ Readings - September 19, 2023

Temperature: The indoor temperatures ranged from 68.7 to 75.3 °F. The indoor temperatures were below the ASHRAE recommended range.

Relative Humidity: The indoor relative humidity ranged from 57.6 to 72.4 percent. Some of the relative humidity readings were above the ASHRAE recommended range of 20 to 60 percent relative humidity.

Carbon Monoxide: Indoor carbon monoxide concentrations ranged from ppm 0.7 to 1.0 ppm. These concentrations are below the OSHA PEL limit.

Carbon Dioxide: The outside carbon dioxide concentration recorded on this day was 436 ppm. The indoor concentrations ranged from 552 to 1271 ppm. The difference between the highest indoor concentration and the outdoor concentration was 834 ppm. This is slightly above the recommended difference of less than 707 ppm. Additionally, carbon dioxide concentrations were well below the OSHA permissible exposure limit.

Particulates in Air (Dust): The indoor concentration of particulates in air inside the building did not exceed 0.033 mg/m3. The concentration of particulates in air inside the building was well below the OSHA PEL at the time of the assessment.

Volatile Organic Compounds (VOCs): VOC readings ranged from 0.0 to 0.466 which is below the standard of 0.5 ppm.

Formaldehyde: Formaldehyde levels did not exceed 0.00 ppm throughout the testing. This concentration is below the OSHA formaldehyde limit.

IAQ Readings - September 20, 2023

Temperature: The indoor temperatures ranged from 69.4 to 74.7 °F. The indoor temperatures were generally within the ASHRAE recommended range.

Relative Humidity: The indoor relative humidity ranged from 51.0 to 64.5 percent. Some of the relative humidity readings were above the ASHRAE recommended range of 20 to 60 percent relative humidity.

Carbon Monoxide: Indoor carbon monoxide concentrations ranged from ppm 0.6 to 1.1 ppm. This concentration is below the OSHA PEL limit.

Carbon Dioxide: The outside carbon dioxide concentration recorded on this day was 553 ppm. The indoor concentrations ranged from 555 to 1343 ppm. The difference between the highest indoor concentration and the outdoor concentration was 790 ppm. This is slightly above the recommended difference of less than 707 ppm. Additionally, carbon dioxide concentrations were well below the OSHA permissible exposure limit.

Particulates in Air (Dust): The indoor concentration of particulates in air inside the building did not exceed 0.000 mg/m3. The concentration of particulates in air inside the building was well below the OSHA PEL at the time of the assessment.

Volatile Organic Compounds (VOCs): VOC readings ranged from 0.0 to 0.535 which is slightly above the standard of 0.5 ppm.

Formaldehyde: Formaldehyde levels did not exceed 0.00 ppm throughout the testing. This concentration is below the OSHA formaldehyde limit.

IAQ Readings - September 21, 2023

Temperature: The indoor temperatures ranged from 69.2 to 74.8 °F. The indoor temperatures were generally within the ASHRAE recommended range.

Relative Humidity: The indoor relative humidity ranged from 46.9 to 63.5 percent. Some of the relative humidity readings were above the ASHRAE recommended range of 20 to 60 percent relative humidity.

Carbon Monoxide: Indoor carbon monoxide concentrations ranged from 0.7 - 1.3 ppm. This concentration is below the OSHA PEL limit.

Carbon Dioxide: The outside carbon dioxide concentration recorded on this day was 572 ppm. The indoor concentrations ranged from 578 to 1566 ppm. The difference between the highest indoor concentration and the outdoor concentration was 994 ppm. This is above the recommended difference of less than 707 ppm. Additionally, carbon dioxide concentrations were well below the OSHA permissible exposure limit.

Particulates in Air (Dust): The indoor concentration of particulates were not measured on this day.

Volatile Organic Compounds (VOCs): VOC readings ranged from 0.092 to 0.566 which is at or slightly above the standard of 0.5 ppm.

Formaldehyde: Formaldehyde levels did not exceed 0.00ppm throughout the testing. This concentration is below the OSHA formaldehyde limit.

IAQ Readings - September 22, 2023

Temperature: The indoor temperatures ranged from 67.4 to 82.1 °F. The indoor temperatures were generally within the ASHRAE recommended range.

Relative Humidity: The indoor relative humidity ranged from 52.8 to 76.2 percent. Some of the relative humidity readings were above the ASHRAE recommended range of 20 to 60 percent relative humidity.

Carbon Monoxide: Indoor carbon monoxide concentrations did not exceed 1.3 ppm. This concentration is below the OSHA PEL limit.

Carbon Dioxide: The outside carbon dioxide concentration recorded on this day was 514 ppm. The indoor concentrations ranged from 552 to 1316 ppm. The difference between the highest indoor concentration and the outdoor concentration was 802 ppm. This is above the recommended difference of less than 707 ppm. Additionally, carbon dioxide concentrations were well below the OSHA permissible exposure limit.

Particulates in Air (Dust): The indoor concentration of particulates were not measured on this day.

Volatile Organic Compounds (VOCs): VOC readings ranged from 0.004 to 0.388 which is below the standard of 0.5 ppm.

Formaldehyde: Formaldehyde levels did not exceed 0.00ppm throughout the testing. This concentration is below the OSHA formaldehyde limit.

Air-O-Cell Spore Trap Sampling Results

There are currently no federal or State of Connecticut regulatory standards for concentrations of mold in air. However, some commonly used guidelines have been established. Commonly accepted guidelines of 2,500 counts/m³ for commercial buildings and 5,000 counts/m³ for residential buildings ("Assessment and Sampling Approaches for Indoor Microbiological Assessments" by G. Clark, published in *The Synergist*, November 2001) can be considered valid for air quality assessment purposes. Any spore counts significantly higher than the accompanying baseline sample may indicate a source of fungal amplification.

Microbial Organism Descriptions:

Alternaria: Common allergens that are associated with hypersensitivity pneumonitis. This species can also produce mycotoxins that are associated with human disease.

Ascospores: Health effects are poorly studied, but spores are likely to be allergenic.

Aspergillus/Penicillium: Common allergens that are associated with hypersensitivity pneumonitis. These species can also produce mycotoxins that are associated with human disease.

Basidiospores: Common allergens that are associated with hypersensitivity pneumonitis. **Cladosporium:** Common allergens that are associated with hypersensitivity pneumonitis.

Curvularia: Common allergens and a common cause of allergic fungal sinusitis.

Epicoccum: Common allergens with no reported cases of infection in humans.

Myxomycetes: Some allergenic properties are reported, but spores pose no threat to human health.

Nigrospora: Health effects are poorly studied.

Pithomyces: Allergenic properties are poorly studied with no reported cases of infection in humans.

Polythrincium: No known health or allergenic effects.

Air-O-Cell Sampling Results – September 18, 2023

Sample ID: A2 Sample Location: Lower Level – Automotive Classroom

Significantly high levels of *Cladosporium* were present in this sample. Spore counts and volumes indicated a source of fungal amplification of this genus in this location.

Low levels of *Aspergillus/Penicillium* were also present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A3 Sample Location: Lower Level – A Wing Lobby (near Exit 23)

Low levels of *Basidiospores* and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A4 Sample Location: 1st Floor – E Wing Common Area

Low levels of *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A5

Sample Location: 1st Floor - Main Entrance Lobby

Low levels of *Cladosporium*, *Curvularia*, *Epicoccum*, *Myxomycetes*, and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A6

Sample Location: 1st Floor - Cafeteria

Low levels of *Epicoccum, Myxomycetes*, and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A7

Sample Location: 2nd Floor – Library

Low levels of *Aspergillus/Penicillium*, *Cladosporium*, *Myxomycetes*, and *Rusts/Smuts* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A8

Sample Location: 2nd Floor – 9th Grade Dean's Office (E-212)

Low levels of *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A9

Sample Location: 3rd Floor – Class E-347

Low levels of *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A10

Sample Location: 3rd Floor - A Wing Hallway near Stairwell

Low levels of *Ascospores, Curvularia, Myxomycetes, Epicoccum*, and *Rusts/Smuts* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Air-O-Cell Sampling Results - September 19, 2023

Sample ID: A12

Sample Location: Lower Level - E Wing Hall / Lobby Area

Low levels of *Ascospores, Aspergillus/Pencillium, Basidiospores, Cladosporium* and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A13 Sample Location: Lower Level – Class A-006

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A14 Sample Location: 1st Floor – Class E-132

Low levels of *Ascospores* and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A15 Sample Location: 1st Floor – Main Office

Low levels of *Ascospores, Aspergillus/Penicillium* and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A16 Sample Location: Lower Level – Gymnasium

Low levels of *Ascospores, Aspergillus/Penicillium* and *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A17 Sample Location: 2nd Floor – A Wing Teacher's Lounge

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A18 Sample Location: 2nd Floor – Class E-204

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A19 Sample Location: 3rd Floor – Class E-336

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A20 Sample Location: 3rd Floor – Class A-303

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Air-O-Cell Sampling Results – September 20, 2023

Sample ID: A22 Sample Location: Lower Level – Class A-014

Low levels of *Ascospores* and *Cladosporium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A23 Sample Location: 1st Floor – Class E-133

Low levels of *Basidiospores* and *Cladosporium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A24 Sample Location: 1st Floor – Pupil Services (A-124 & A-142)

Low levels of *Ascospores, Basidiospores* and *Cladosporium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A25 Sample Location: Lower Level – Weight Room

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A26 Sample Location: 1st Floor – Class D-107

Low levels of *Basidiospores* and *Cladosporium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A27 Sample Location: 2nd Floor – Stair C-ST1

Low levels of *Ascospores, Myxomycetes*, and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A28

Sample Location: 2nd Floor - Class E-201

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A29

Sample Location: 3rd Floor - Class E-337

Low levels of *Myxomycetes* and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A30

Sample Location: 3rd Floor - Class A-301

Low levels of *Ascospores, Basidiospores*, and *Cladosporium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Air-O-Cell Sampling Results - September 21, 2023

Sample ID: A31

Sample Location: Classroom A-106

Low levels of *Ascospores* and *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A32

Sample Location: 1st Floor - Stair E-ST2

Low levels of *Ascospores, Aspergillus/Penicillium, Basidiospores, Curvularia, Epicoccum, Myxomycetes,* and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A33

Sample Location: Cafeteria

Low levels of *Ascospores, Aspergillus/Penicillium*, and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A34

Sample Location: Gym Office

Low levels of *Ascospores, Aspergillus/Penicillium*, and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A35

Sample Location: Pre-School Classroom A-005

Low levels of *Ascospores, Aspergillus/Penicillium*, and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A36

Sample Location: Classroom E-212

Low levels of *Ascospores, Aspergillus/Penicillium, Basidiospores, Myxomycetes*, and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A37

Sample Location: Classroom A-234

Low levels of *Ascospores, Basidiospores*, and *Polythrincium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A38

Sample Location: 3rd Floor – Vice Principal's Office

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A39

Sample Location: Classroom A-33A

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Air-O-Cell Sampling Results - September 22, 2023

Sample ID: A41

Sample Location: Classroom A-106

Low levels of *Alternaria*, *Ascospores*, and *Cladosporium* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A42

Sample Location: Cafeteria Kitchen

Low levels of *Ascospores* and *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A43 Sample Location: Classroom Across C-012

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A44 Sample Location: Ticket Booth Office

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A45 Sample Location: Stairwell Near Exit 5

Low levels of *Ascospores, Basidiospores*, and *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A46 Sample Location: Classroom E-221

Low levels of *Ascospores* and *Basidiospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A47 Sample Location: Classroom A-226

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A48 Sample Location: Hallway Ledge near Class E-332

Low levels of *Ascospores* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Sample ID: A49 Sample Location: Elevator No. 049-0124

Low levels of *Ascospores, Myxomycetes*, and *Pithomyces* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of these genera in this location.

Sample ID: A1

Sample Location: Lower Level | Automotive Classroom

Low levels of *Cladosporium* and *Myxomycetes* were present in this sample. Spore counts and volumes were low and did not indicate a source of fungal amplification of this genus in this location.

Based on the results and observations made during the indoor air quality testing on August 2, 2023 at Enfield High school, EnviroMed Services, Inc. has come to the following conclusions and recommendations.

Conclusions from September 18th to September 22nd, 2023

- The indoor temperature was generally within the recommended ASHRAE standard range at the time of the assessment. Indoor temperatures were often slightly below the recommended ASHRAE range in the morning readings.
- The relative humidity was generally above the recommended range of the referenced ASHRAE standard of 20 to 60 percent for relative humidity and was also above the EPA recommended range.
 - Extended duration of high indoor air levels of relative humidity above 60% may result in mold growth and unacceptable indoor air quality comfort levels.
- The average Carbon Dioxide concentration for the five days was between 568 ppm and 1368 ppm, indicating the need for additional building ventilation. The indoor air CO₂ levels were generally more than 707 ppm higher than outdoor CO₂ levels in accordance with ASHRAE standards.
 - Additional outdoor air is required to improve comfort parameters for students and staff.
- Dust concentrations throughout the building were well below the respirable and total PELs of 5 mg/m³ and 15 mg/m³, respectively, indicating no active dust amplification.
- VOC concentrations were generally below the referenced LEED standard of 500 ppb with some exceedances being slightly above the recommended standard of 500 ppb.
- All air mold sample results were within the commonly accepted guideline of 5,000 counts/m³ for residential buildings (Article in *The Synergist* titled, "Assessment and Sampling Approaches for Indoor Microbiological Assessments", G. Clark, published November 2001). The airborne spore trap results inside were overall similar to those levels and types of molds found in the outside air from the baselines.

- On Day 1, LL. Automotive Classroom was found to contain significant amplification of Cladosporium. These noted molds were not detected in any other sample locations during the testing period.
 - This represents an unacceptable finding requiring mold remediation of this area in the school facility.
- The detected formaldehyde concentrations were well below the OSHA PEL of 0.75 ppm.

Recommendations

Relative humidity and carbon dioxide levels throughout the school were found to be above the recommended standards for indoor air quality. In order to decrease the levels for these parameters, additionally outdoor air ventilation is required. This can be achieved by improving the school's current HVAC system.

EnviroMed Services also identified an exceedance of and an amplification of *Cladosporium* in the LL. Automotive Classroom.

EnviroMed Services recommends that a professional remediation contractor clean all cleanable nonporous surfaces with a disinfecting agent such as Fiberlock ShockWave or equivalent in the affected area of the LL. Automotive Classroom, in addition, EnviroMed Services, Inc. recommends the use of an air scrubbing system to remove all airborne spores. We also recommend the use of a HEPA (High-Efficiency Particulate Air) vacuum. Prior to cleaning, a Negative Air Pressure Containment setup will be required to prevent the contamination of any airborne mold spores during the remediation process. Containment air to be exhausted outside containment area during remediation. The HEPA Sandwich method (vacuum/ clean/ vacuum) is recommended with the continued use of an industrial HEPA Air Unit for at least 24 hours' post abatement work to further clean the air.

Following the cleaning, EnviroMed recommends a follow-up microbial assessment be performed by a professional industrial hygienist to verify the effectiveness of the cleaning.

There were no sources of fungal amplification or active mold growth in any of the remaining spaces tested throughout Enfield High School during the five (5) days of testing. This school is fit for occupancy as there was no other evidence of mold contamination or presence of toxigenic mold.

Based on the results and observations made during the indoor air quality testing on November 7, 2023, at Enfield High School, EnviroMed Services, Inc. has come to the following conclusions and recommendations.

Conclusions from November 7, 2023

- On September 18, 2023, LL. Automotive Classroom was found to contain significant amplification of Cladosporium. These noted molds were not detected in any other sample locations during that testing period.
 - This represented an unacceptable finding requiring mold remediation of this area in the school facility.
- On November 7, 2023, the airborne spore trap results inside the Automotive Classroom were overall similar to those levels and types of molds found in the outside air from the baseline.

Recommendations

There were no longer sources of fungal amplification or active mold growth in the Automotive Classroom in Enfield High School. This room is fit for occupancy as there was no other evidence of mold contamination or presence of toxigenic mold.

II. TABLE OF IAQ MEASUREMENTS

IAQ Readings taken on September 18, 2023

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|---|-------|--------|----------|-----------------------|----------------------------|-----------|--------------------|
| Outside | 67.2 | 83.0 | 1.2 | 558 | 0.0 | 0.0 | 0.000 |
| Lower Level – E Wing Hall | 70.0 | 69.5 | 0.9 | 842 | 0.0 | 0.246 | 0.000 |
| LL – Wood Technology | 70.0 | 80.2 | 1.0 | 778 | 0.0 | 0.129 | 0.000 |
| LL- Automotive Classroom | 70.4 | 75.9 | 1.2 | 899 | 0.0 | 0.136 | 0.000 |
| LL – A Wing Hall | 69.8 | 67.4 | 1.0 | 936 | 0.0 | 0.152 | 0.000 |
| LL – Classroom A-006 | 60.6 | 63.2 | 0.8 | 830 | 0.0 | 0.158 | 0.000 |
| LL – A Wing Lobby Near Exit 23 | 68.5 | 67.3 | 0.8 | 930 | 0.0 | 0.155 | 0.000 |
| LL – Classroom A-014 | 68.2 | 63.6 | 0.8 | 756 | 0.0 | 0.140 | 0.000 |
| LL - Mechanical/Storage | 71.6 | 67.0 | 0.8 | 658 | 0.0 | 0.132 | 0.000 |
| 1 st Floor – E Wing Exit 5 Door | 70.0 | 64.4 | 0.8 | 824 | 0.0 | 0.151 | 0.015 |
| 1st Floor – Class E-129 | 70.2 | 64.0 | 0.9 | 787 | 0.0 | 0.129 | 0000 |
| 1st Floor – E Wing Common Area | 70.5 | 64.0 | 0.8 | 1028 | 0.0 | 0.136 | 0.013 |
| 1st Floor – Class E-132 | 71.2 | 63.3 | 0.7 | 914 | 0.0 | 0.118 | 0.000 |
| 1st Floor - A Wing Hall | 71.3 | 62.5 | 1.0 | 984 | 0.0 | 0.142 | 0.015 |
| 1st Floor – Class A-160 | 69.6 | 59.2 | 1.0 | 764 | 0.0 | 0.113 | 0.002 |
| 1st Floor – Main Lobby | 71.1 | 62.7 | 0.8 | 806 | 0.0 | 0.129 | 0.005 |
| 1st Floor – Main Office | 71.6 | 60.0 | 0.9 | 690 | 0.0 | 0.247 | 0.001 |
| 1st Floor - Pupil Services | 72.0 | 63.1 | 1.0 | 995 | 0.0 | 0.307 | 0.000 |
| 1st Floor – Career Center | 72.0 | 63.6 | 0.8 | 985 | 0.0 | 0.198 | 0.000 |
| 1st Floor – Class C-123 | 71.8 | 71.0 | 0.9 | 913 | 0.0 | 0.166 | 0.000 |
| LL – Gym Lobby | 71.8 | 71.0 | 0.8 | 789 | 0.0 | 0.137 | 0.000 |
| LL – Gym | 71.1 | 70.3 | 1.0 | 755 | 0.0 | 0.090 | 0.000 |
| LL – Weight Room | 67.8 | 65.6 | 0.8 | 717 | 0.0 | 0.131 | 0.000 |
| 1st Floor – Cafeteria | 68.5 | 72.8 | 0.7 | 1130 | 0.0 | 0.141 | 0.000 |
| 1st Floor - C Wing Hall | 68.6 | 75.8 | 0.7 | 862 | 0.0 | 0.115 | 0.000 |
| 1st Floor – D Wing Hall | 69.5 | 76.5 | 0.7 | 742 | 0.0 | 0.080 | 0.000 |
| 1st Floor – Auditorium | 69.3 | 80.5 | 0.7 | 605 | 0.0 | 0.049 | 0.000 |
| 1st Floor – Class D-125 | 69.2 | 74.9 | 0.9 | 964 | 0.0 | 0.102 | 0.000 |
| 2 nd Floor – A Wing Hall | 71.6 | 67.2 | 0.9 | 1174 | 0.0 | 0.163 | 0.000 |
| 2 nd Floor – Library | 71.9 | 61.0 | 1.0 | 777 | 0.0 | 0.132 | 0.000 |
| 2 nd Floor – Class A-226 | 71.4 | 56.5 | 0.8 | 1053 | 0.0 | 0.154 | 0.000 |
| 2 nd Floor – Class A-202 | 71.6 | 55.2 | 0.8 | 883 | 0.0 | 0.158 | 0.000 |
| 2 nd Floor – E Wing Hall | 71.8 | 60.1 | 0.9 | 985 | 0.0 | 0.176 | 0.000 |

| | Temp. | DYY (0/) | 60 (| CO ₂ | CH ₂ O | VOC | Dust Conc. |
|--|-------|----------|----------|-----------------|-------------------|-------|-------------------|
| Location | (°F) | RH (%) | CO (ppm) | (ppm) | (ppm) | (ppm) | (mg/m^3) |
| 2 nd Floor – Class E-204 | 70.9 | 61.2 | 1.1 | 753 | 0.0 | 0.174 | 0.000 |
| 2 nd Floor – Dean's Office E- 212 | 71.7 | 60.5 | 0.7 | 707 | 0.0 | 0.124 | 0.000 |
| 2 nd Floor – Class E-235 | 71.7 | 62.6 | 0.8 | 1083 | 0.0 | 0.165 | 0.000 |
| 2 nd Floor – E Wing Stairwell | 71.3 | 61.8 | 0.8 | 996 | 0.0 | 0.154 | 0.012 |
| 3 rd Floor – Class E-347 | 71.5 | 60.6 | 0.7 | 831 | 0.0 | 0.160 | 0.000 |
| 3 rd Floor – E Wing Hall | 72.1 | 61.6 | 0.7 | 1096 | 0.0 | 0.174 | 0.006 |
| 3 rd Floor – Assistant Principals Office | 72.5 | 60.7 | 0.8 | 956 | 0.0 | 0.152 | 0.000 |
| 3 rd Floor – ENN Room | 72.6 | 58.9 | 0.8 | 855 | 0.0 | 0.144 | 0.004 |
| 3 rd Floor – Class E-328 | 72.3 | 60.0 | 0.8 | 886 | 0.0 | 0.147 | 0.007 |
| 3 rd Floor – A Wing Hall | 72.8 | 60.8 | 0.8 | 1125 | 0.0 | 0.172 | 0.000 |
| 3 rd Floor – A Wing Stairwell | 74.7 | 62.9 | 1.0 | 1103 | 0.0 | 0.141 | 0.012 |
| 3rd Floor - Class A-308 | 74.8 | 57.7 | 1.1 | 1344 | 0.0 | 0.182 | 0.000 |
| 3rd Floor – Class A-306 | 73.5 | 57.5 | 1.2 | 1229 | 0.0 | 0.183 | 0.000 |
| 3rd Floor – Class A-304 | 72.6 | 57.8 | 1.2 | 1317 | 0.0 | 0.183 | 0.000 |
| Lower Level – E Wing Hall | 70.5 | 63.4 | 0.8 | 816 | 0.0 | 0.116 | 0.004 |
| LL – Wood Technology | 70.0 | 75.7 | 0.7 | 830 | 0.0 | 0.079 | 0.000 |
| LL- Automotive Classroom | 69.8 | 68.7 | 0.9 | 705 | 0.0 | 0.125 | 0.000 |
| LL – A Wing Hall | 70.1 | 65.5 | 0.7 | 942 | 0.0 | 0.119 | 0.000 |
| LL – Classroom A-006 | 68.1 | 60.9 | 0.8 | 694 | 0.0 | 0.091 | 0.000 |
| LL – A Wing Lobby Near Exit 23 | 68.6 | 63.9 | 0.8 | 768 | 0.0 | 0.105 | 0.000 |
| LL – Classroom A-014 | 68.8 | 62.7 | 0.7 | 810 | 0.0 | 0.100 | 0.000 |
| LL - Mechanical/Storage | 70.5 | 69.9 | 0.7 | 741 | 0.0 | 0.111 | 0.000 |
| 1 st Floor – E Wing Exit 5 Doors | 69.8 | 62.7 | 0.7 | 765 | 0.0 | 0.108 | 0.000 |
| 1st Floor – Class E-129 | 70.3 | 62.5 | 0.7 | 834 | 0.0 | 0.110 | 0.000 |
| 1st Floor – E Wing Common Area | 70.5 | 62.5 | 0.8 | 832 | 0.0 | 0.117 | 0.007 |
| 1st Floor – Class E-132 | 70.8 | 62.7 | 0.7 | 858 | 0.0 | 0.106 | 0.000 |
| 1st Floor - A Wing Hall | 71.1 | 62.3 | 0.7 | 1025 | 0.0 | 0.141 | 0.000 |
| 1st Floor – Class A-160 | 71.0 | 60.9 | 0.8 | 871 | 0.0 | 0.137 | 0.000 |
| 1st Floor – Main Lobby | 71.9 | 61.7 | 0.7 | 850 | 0.0 | 0.136 | 0.000 |
| 1st Floor – Main Office | 71.7 | 59.9 | 0.8 | 802 | 0.0 | 0.127 | 0.000 |
| 1st Floor - Pupil Services | 71.7 | 63.7 | 0.9 | 917 | 0.0 | 0.133 | 0.000 |
| 1st Floor – Career Center | 71.7 | 64.3 | 0.9 | 676 | 0.0 | 0.128 | 0.000 |
| 1st Floor – Class C-123 | 71.5 | 64.2 | 0.9 | 707 | 0.0 | 0.120 | 0.000 |
| LL – Gym Lobby | 71.8 | 72.6 | 1.0 | 810 | 0.0 | 0.130 | 0.000 |
| LL – Gym | 70.4 | 71.6 | 0.8 | 675 | 0.0 | 0.111 | 0.000 |

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|--|-------|--------|----------|-----------------------|----------------------------|--------------|-----------------------|
| LL – Weight Room | 66.5 | 65.9 | 0.7 | 802 | 0.0 | 0.130 | 0.00 |
| 1st Floor – Cafeteria | 65.4 | 75.0 | 0.7 | 659 | 0.0 | 0.168 | 0.00 |
| 1st Floor - C Wing Hall | 69.6 | 81.5 | 0.7 | 639 | 0.0 | 0.122 | 0.00 |
| 1st Floor – D Wing Hall | 70.3 | 80.8 | 0.8 | 625 | 0.0 | 0.111 | 0.00 |
| 1st Floor – Auditorium | 96.6 | 79.2 | 0.8 | 661 | 0.0 | 0.113 | 0.00 |
| 1st Floor – Class D-125 | 69.9 | 80.6 | 0.7 | 803 | 0.0 | 0.134 | 0.00 |
| 2 nd Floor – A Wing Hall | 72.1 | 71.4 | 0.7 | 787 | 0.0 | 0.208 | 0.00 |
| 2 nd Floor – Library | 71.6 | 61.1 | 0.7 | 897 | 0.0 | 0.202 | 0.00 |
| 2 nd Floor – Class A-226 | 71.7 | 61.8 | 0.9 | 929 | 0.0 | 0.254 | 0.00 |
| 2 nd Floor – Class A-202 | 72.0 | 57.2 | 0.7 | 867 | 0.0 | 0.218 | 0.00 |
| 2 nd Floor – E Wing Hall | 72.0 | 61.5 | 0.8 | 910 | 0.0 | 0.280 | 0.00 |
| 2 nd Floor – Class E-204 | 71.4 | 60.1 | 0.7 | 767 | 0.0 | 0.251 | 0.00 |
| 2 nd Floor – Dean's Office E- 212 | 71.2 | 61.5 | 0.7 | 719 | 0.0 | 0.305 | 0.00 |
| 2 nd Floor – Class E-235 | 71.4 | 61.8 | 0.7 | 773 | 0.0 | 0.265 | 0.00 |
| 2 nd Floor – E Wing Stairwell | 71.2 | 60.8 | 0.7 | 720 | 0.0 | 0.298 | 0.00 |
| 3 rd Floor – Class E-347 | 72.0 | 61.2 | 0.8 | 806 | 0.0 | 0.209 | 0.00 |
| 3 rd Floor – E Wing Hall | 72.1 | 59.2 | 0.7 | 755 | 0.0 | 0.297 | 0.00 |
| 3 rd Floor – Assistant Principals Office | 72.0 | 61.6 | 0.7 | 921 | 0.0 | 0.317 | 0.00 |
| 3 rd Floor – ENN Room | 72.2 | 58.9 | 0.7 | 756 | 0.0 | 0.303 | 0.00 |
| 3 rd Floor – Class E-328 | 71.5 | 58.5 | 0.7 | 751 | 0.0 | 0.322 | 0.00 |
| 3 rd Floor – A Wing Hall | 72.4 | 63.5 | 0.7 | 661 | 0.0 | 0.303 | 0.00 |
| 3 rd Floor – A Wing Stairwell | 73.7 | 59.5 | 0.7 | 712 | 0.0 | 0.322 | 0.00 |
| 3 rd Floor – Class A-306 | 73.6 | 54.7 | 0.8 | 646 | 0.0 | 0.368 | 0.00 |
| 3 rd Floor – Class A-304 | 72.7 | 55.4 | 0.8 | 813 | 0.0 | 0.375 | 0.00 |

IAQ Readings taken on September 19, 2023

| | Temp. | | | CO ₂ | CH ₂ O | VOC | Dust Conc. |
|---|-------|--------|----------|-----------------|-------------------|-------|-------------------|
| Location | (°F) | RH (%) | CO (ppm) | (ppm) | (ppm) | (ppm) | (mg/m^3) |
| Outside | 65.8 | 65.0 | 0.7 | 436 | 0.0 | 0.0 | 0.000 |
| Lower Level – E Wing Hall | 70.7 | 68.4 | 0.7 | 835 | 0.0 | 0.034 | 0.000 |
| LL – E Wing Men's Bathroom | 71.0 | 68.6 | 0.7 | 827 | 0.0 | 0.047 | 0.000 |
| LL – E Wing Women's Bathroom | 70.8 | 68.7 | 0.8 | 939 | 0.0 | 0.066 | 0.000 |
| LL – Automotive Class | 70.3 | 70.8 | 0.8 | 825 | 0.0 | 0.119 | 0.000 |
| LL – A Wing Hall | 70.3 | 70.8 | 0.8 | 995 | 0.0 | 0.114 | 0.000 |
| LL – A Wing Lobby | 70.9 | 68.5 | 0.7 | 915 | 0.0 | 0.093 | 0.000 |
| LL – Class A-006 | 70.6 | 67.7 | 0.8 | 806 | 0.0 | 0.098 | 0.000 |
| LL – Class A-015 | 70.6 | 68.7 | 0.7 | 878 | 0.0 | 0.145 | 0.000 |
| LL – A Wing Stairwell | 70.8 | 68.0 | 0.7 | 837 | 0.0 | 0.136 | 0.000 |
| 1st Floor – E Wing Hall | 71.3 | 68.6 | 0.7 | 924 | 0.0 | 0.176 | 0.017 |
| 1st Floor – Class E-106 | 71.8 | 67.6 | 0.7 | 992 | 0.0 | 0.176 | 0.033 |
| 1st Floor – Class E-132 | 72.9 | 66.6 | 0.7 | 760 | 0.0 | 0.180 | 0.000 |
| 1 st Floor – E Wing Common Area | 73.1 | 64.7 | 0.7 | 816 | 0.0 | 0.204 | 0.022 |
| 1st Floor – Class E-127 | 72.5 | 65.3 | 1.0 | 767 | 0.0 | 0.200 | 0.012 |
| 1st Floor – A Wing Hall | 72.4 | 65.8 | 0.9 | 859 | 0.0 | 0.208 | 0.110 |
| 1st Floor – Class A-101 | 72.5 | 65.3 | 0.7 | 821 | 0.0 | 0.196 | 0.000 |
| 1st Floor – Class A-160 | 72.3 | 65.1 | 0.7 | 770 | 0.0 | 0.203 | 0.000 |
| 1st Floor – Main Office | 72.6 | 66.7 | 0.7 | 841 | 0.0 | 0.205 | 0.000 |
| 1st Floor – Main Entry Lobby | 72.9 | 66.1 | 0.7 | 939 | 0.0 | 0.235 | 0.000 |
| 1st Floor – Pupil Services | 73.2 | 66.1 | 0.7 | 879 | 0.0 | 0.221 | 0.000 |
| 1st Floor – Grade 12 Office | 73.7 | 66.4 | 0.7 | 1095 | 0.0 | 0.310 | 0.000 |
| 1st Floor – Guidance Office | 73.4 | 65.1 | 0.7 | 844 | 0.0 | 0.221 | 0.000 |
| 1st Floor – Class C-123 | 73.1 | 65.3 | 0.9 | 865 | 0.0 | 0.224 | 0.000 |
| 1st Floor – C Wing Hall | 72.8 | 65.3 | 0.7 | 707 | 0.0 | 0.174 | 0.000 |
| LL – Gym | 70.4 | 64.8 | 0.7 | 630 | 0.0 | 0.135 | 0.000 |
| LL – Gym Office | 70.9 | 66.9 | 0.7 | 637 | 0.0 | 0.166 | 0.000 |
| LL – Cardio Room | 70.9 | 71.0 | 0.7 | 574 | 0.0 | 0.129 | 0.003 |
| LL – Lobby near Exit 34 | 70.9 | 67.1 | 0.7 | 675 | 0.0 | 0.178 | 0.000 |
| 1st Floor – Cafeteria | 72.3 | 72.4 | 0.8 | 1221 | 0.0 | 0.264 | 0.000 |
| 1st Floor – Auditorium | 70.6 | 63.3 | 0.7 | 613 | 0.0 | 0.137 | 0.000 |
| 1st Floor – D Wing | 70.0 | 68.2 | 0.8 | 571 | 0.0 | 0.132 | 0.000 |
| 1st Floor – Class D-107 | 70.1 | 67.6 | 0.7 | 855 | 0.0 | 0.270 | 0.000 |

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|--|-------|--------|----------|-----------------------|----------------------------|-----------|-----------------------|
| 2 nd Floor – Library | 71.9 | 65.8 | 0.7 | 855 | 0.0 | 0.270 | 0.000 |
| 2 nd Floor – A Wing Teacher's Lounge | 74.4 | 65.0 | 0.7 | 761 | 0.0 | 0.271 | 0.000 |
| 2 nd Floor – A Wing Hall | 75.3 | 62.8 | 0.8 | 1270 | 0.0 | 0.335 | 0.000 |
| 2 nd Floor – Class A-211 | 73.8 | 61.3 | 0.9 | 819 | 0.0 | 0.308 | 0.000 |
| 2 nd Floor – Class A-206 | 73.1 | 61.2 | 1.0 | 855 | 0.0 | 0.313 | 0.000 |
| 2 nd Floor – E Wing Hall | 73.1 | 62.7 | 0.7 | 1167 | 0.0 | 0.314 | 0.000 |
| 2 nd Floor – Class E-204 | 71.5 | 61.6 | 0.7 | 833 | 0.0 | 0.351 | 0.000 |
| 2 nd Floor – Class E-205 | 71.4 | 62.2 | 0.7 | 822 | 0.0 | 0.313 | 0.000 |
| 2 nd Floor – Class E-234 | 71.8 | 62.6 | 0.7 | 802 | 0.0 | 0.300 | 0.000 |
| 2 nd Floor – E Wing Stairwell | 72.0 | 61.8 | 0.7 | 821 | 0.0 | 0.314 | 0.000 |
| 3 rd Floor – Class E-336 | 72.8 | 61.6 | 0.7 | 838 | 0.0 | 0.310 | 0.000 |
| 3 rd Floor – E Wing Hall | 73.2 | 61.4 | 0.8 | 946 | 0.0 | 0.325 | 0.000 |
| 3 rd Floor – Class E-317 | 73.4 | 61.4 | 0.8 | 932 | 0.0 | 0.331 | 0.000 |
| 3rd Floor – E Wing Stairwell | 74.0 | 60.4 | 0.7 | 931 | 0.0 | 0.370 | 0.000 |
| 3 rd Floor – A Wing Hall | 73.4 | 60.6 | 0.7 | 1026 | 0.0 | 0.385 | 0.000 |
| 3 rd Floor – Class A-303 | 72.0 | 57.6 | 0.7 | 733 | 0.0 | 0.355 | 0.000 |
| 3 rd Floor – Class A-321 | 72.4 | 62.0 | 0.7 | 1254 | 0.0 | 0.430 | 0.000 |
| 3rd Floor – Class A-313 | 73.1 | 60.6 | 0.8 | 990 | 0.0 | 0.434 | 0.000 |
| Lower Level – E Wing Hall | 70.0 | 64.0 | 0.7 | 798 | 0.0 | 0.034 | 0.000 |
| LL – E Wing Men's Bathroom | 69.9 | 63.3 | 0.7 | 782 | 0.0 | 0.034 | 0.000 |
| LL – E Wing Women's Bathroom | 70.0 | 65.1 | 0.7 | 854 | 0.0 | 0.046 | 0.000 |
| LL – Automotive Class | 70.0 | 64.9 | 0.7 | 722 | 0.0 | 0.056 | 0.000 |
| LL – A Wing Hall | 69.9 | 63.3 | 0.7 | 908 | 0.0 | 0.052 | 0.000 |
| LL – A Wing Lobby | 69.3 | 62.6 | 0.8 | 753 | 0.0 | 0.100 | 0.000 |
| LL – Class A-006 | 68.7 | 63.1 | 0.7 | 884 | 0.0 | 0.114 | 0.000 |
| LL – Class A-015 | 69.1 | 62.9 | 0.8 | 772 | 0.0 | 0.133 | 0.000 |
| LL – A Wing Stairwell | 69.6 | 64.2 | 0.7 | 874 | 0.0 | 0.135 | 0.000 |
| 1st Floor – E Wing Hall | 70.1 | 63.7 | 0.7 | 815 | 0.0 | 0.173 | 0.000 |
| 1st Floor – Class E-106 | 70.6 | 63.7 | 0.7 | 881 | 0.0 | 0.176 | 0.000 |
| 1st Floor – Class E-132 | 71.5 | 63.2 | 0.7 | 805 | 0.0 | 0.151 | 0.000 |
| 1st Floor – E Wing Common Area | 71.7 | 31.6 | 0.7 | 910 | 0.0 | 0.185 | 0.000 |
| 1st Floor – Class E-127 | 71.0 | 62.2 | 0.7 | 822 | 0.0 | 0.190 | 0.000 |
| 1st Floor – A Wing Hall | 71.1 | 61.0 | 0.7 | 847 | 0.0 | 0.224 | 0.000 |
| 1st Floor – Class A-101 | 71.0 | 60.8 | 0.7 | 896 | 0.0 | 0.226 | 0.000 |
| 1st Floor – Class A-160 | 70.6 | 61.3 | 0.7 | 1026 | 0.0 | 0.325 | 0.000 |

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|--|-------|--------|----------|-----------------------|----------------------------|-----------|--------------------|
| 1st Floor – Main Office | 71.1 | 60.8 | 0.8 | 910 | 0.0 | 0.226 | 0.000 |
| 1st Floor – Main Entry Lobby | 71.6 | 60.1 | 0.7 | 708 | 0.0 | 0.240 | 0.000 |
| 1st Floor – Pupil Services | 71.9 | 59.9 | 0.7 | 667 | 0.0 | 0.239 | 0.000 |
| 1 st Floor – Grade 12 Office | 72.4 | 60.5 | 0.7 | 917 | 0.0 | 0.251 | 0.000 |
| 1st Floor – Guidance Office | 71.9 | 59.6 | 0.7 | 771 | 0.0 | 0.235 | 0.000 |
| 1st Floor – Class C-123 | 71.5 | 59.5 | 0.7 | 581 | 0.0 | 0.227 | 0.000 |
| 1st Floor – C Wing Hall | 71.3 | 59.3 | 0.7 | 586 | 0.0 | 0.225 | 0.000 |
| LL – Gym | 71.1 | 61.0 | 0.8 | 588 | 0.0 | 0.208 | 0.000 |
| LL – Gym Office | 71.4 | 60.8 | 0.7 | 619 | 0.0 | 0.221 | 0.000 |
| LL – Cardio Room | 71.2 | 70.5 | 0.7 | 1085 | 0.0 | 0.163 | 0.000 |
| LL – Lobby near Exit 34 | 69.3 | 61.2 | 0.7 | 557 | 0.0 | 0.232 | 0.000 |
| 1st Floor – Cafeteria | 71.2 | 67.6 | 0.7 | 960 | 0.0 | 0.265 | 0.000 |
| 1st Floor – Auditorium | 71.0 | 61.9 | 0.7 | 574 | 0.0 | 0.216 | 0.000 |
| 1st Floor – D Wing | 70.4 | 63.5 | 0.7 | 553 | 0.0 | 0.216 | 0.000 |
| 1st Floor – Class D-107 | 70.6 | 63.1 | 0.7 | 552 | 0.0 | 0.218 | 0.000 |
| 2 nd Floor – Library | 70.2 | 59.5 | 0.7 | 622 | 0.0 | 0.321 | 0.000 |
| 2 nd Floor – A Wing Teacher's Lounge | 72.5 | 58.2 | 0.7 | 664 | 0.0 | 0.372 | 0.000 |
| 2 nd Floor – A Wing Hall | 73.2 | 58.4 | 0.7 | 883 | 0.0 | 0.394 | 0.000 |
| 2 nd Floor – Class A-211 | 73.5 | 58.1 | 0.7 | 815 | 0.0 | 0.397 | 0.000 |
| 2 nd Floor – E Wing Hall | 72.6 | 59.3 | 0.8 | 847 | 0.0 | 0.429 | 0.000 |
| 2 nd Floor – Class E-204 | 72.1 | 60.2 | 0.7 | 742 | 0.0 | 0.424 | 0.000 |
| 2 nd Floor – Class E-205 | 71.6 | 60.1 | 0.7 | 767 | 0.0 | 0.402 | 0.000 |
| 2 nd Floor – Class E-234 | 71.9 | 60.3 | 0.7 | 704 | 0.0 | 0.392 | 0.000 |
| 2 nd Floor – E Wing Stairwell | 71.6 | 59.5 | 0.7 | 748 | 0.0 | 0.407 | 0.000 |
| 3 rd Floor – Class E-336 | 72.3 | 60.0 | 0.7 | 778 | 0.0 | 0.200 | 0.000 |
| 3 rd Floor – E Wing Hall | 72.9 | 59.3 | 0.8 | 755 | 0.0 | 0.415 | 0.000 |
| 3 rd Floor – Class E-317 | 72.5 | 60.0 | 0.7 | 835 | 0.0 | 0.417 | 0.000 |
| 3 rd Floor – E Wing Stairwell | 72.9 | 59.3 | 0.7 | 803 | 0.0 | 0.423 | 0.000 |
| 3 rd Floor – A Wing Hall | 72.5 | 59.3 | 0.8 | 791 | 0.0 | 0.444 | 0.000 |
| 3 rd Floor – Class A-303 | 72.5 | 57.7 | 0.7 | 715 | 0.0 | 0.445 | 0.000 |
| 3 rd Floor – Class A-321 | 72.3 | 57.9 | 0.7 | 703 | 0.0 | 0.466 | 0.000 |
| 3 rd Floor – Class A-313 | 74.1 | 60.5 | 0.7 | 855 | 0.0 | 0.414 | 0.000 |

| | Temp. | | | CO ₂ | CH ₂ O | VOC | Dust Conc. |
|--|-------|--------|----------|-----------------|-------------------|-------|-------------------|
| Location | (°F) | RH (%) | CO (ppm) | (ppm) | (ppm) | (ppm) | (mg/m^3) |
| Outside | 64.0 | 66.5 | 0.8 | 553 | 0.0 | 0 | 0.00 |
| LL – E Wing Hall | 71.1 | 59.3 | 0.8 | 895 | 0.0 | 0.079 | 0.00 |
| LL – Stair E-ST2 | 70.4 | 59.9 | 0.9 | 857 | 0.0 | 0.064 | 0.00 |
| LL – Automotive Class | 70.1 | 61.7 | 1.1 | 1089 | 0.0 | 0.060 | 0.00 |
| LL – A Wing Hall | 69.9 | 61.9 | 0.7 | 1120 | 0.0 | 0.041 | 0.00 |
| LL – Class A-005 | 70.5 | 59.9 | 0.7 | 850 | 0.0 | 0.034 | 0.00 |
| LL – Class A-014 | 73.3 | 56.8 | 0.8 | 775 | 0.0 | 0.028 | 0.00 |
| LL – Stair C-ST1 | 72.3 | 58.5 | 1.0 | 1053 | 0.0 | 0.093 | 0.00 |
| LL – A Wing Lobby Near Exit 23 | 71.1 | 58.1 | 0.9 | 781 | 0.0 | 0.069 | 0.00 |
| 1st Floor – E Wing Hall | 71.7 | 58.9 | 0.7 | 941 | 0.0 | 0.128 | 0.00 |
| 1st Floor – Class E-104 | 71.8 | 57.7 | 0.7 | 871 | 0.0 | 0.136 | 0.00 |
| 1st Floor – Class E-133 | 73.3 | 56.1 | 0.8 | 865 | 0.0 | 0.171 | 0.00 |
| 1st Floor – Class E-105 | 72.7 | 54.7 | 0.8 | 825 | 0.0 | 0.189 | 0.00 |
| 1st Floor – E Wing Common Area | 72.7 | 56.5 | 0.7 | 825 | 0.0 | 0.226 | 0.00 |
| 1st Floor – Class E-127 | 72.5 | 56.8 | 0.7 | 814 | 0.0 | 0.232 | 0.00 |
| 1st Floor – A Wing Hall | 72.0 | 57.6 | 0.8 | 841 | 0.0 | 0.249 | 0.00 |
| 1st Floor – Class A-160 | 71.6 | 57.4 | 0.7 | 799 | 0.0 | 0.266 | 0.00 |
| 1st Floor – Class A-158 | 71.6 | 57.8 | 0.7 | 813 | 0.0 | 0.258 | 0.00 |
| 1 st Floor – Main Entrance Lobby | 71.7 | 57.9 | 0.8 | 764 | 0.0 | 0.251 | 0.00 |
| 1st Floor - Main Office | 72.3 | 57.4 | 0.7 | 765 | 0.0 | 0.243 | 0.00 |
| 1st Floor - Pupil Services | 72.4 | 56.7 | 0.7 | 730 | 0.0 | 0.254 | 0.00 |
| 1st Floor – Stair C-ST1 | 72.8 | 58.1 | 0.7 | 1022 | 0.0 | 0.338 | 0.00 |
| 1st Floor – Career Center | 72.7 | 56.9 | 0.7 | 751 | 0.0 | 0.268 | 0.00 |
| 1st Floor – Class C-123 | 72.7 | 56.9 | 0.7 | 786 | 0.0 | 0.290 | 0.00 |
| LL – Weight Room | 70.1 | 56.7 | 0.8 | 558 | 0.0 | 0.240 | 0.00 |
| LL – Gym Lobby Near Bathroom | 70.3 | 59.9 | 0.7 | 758 | 0.0 | 0.283 | 0.00 |
| LL – Cardio Room | 70.6 | 58.1 | 0.7 | 638 | 0.0 | 0.266 | 0.00 |
| LL – Gym | 71.7 | 60.0 | 0.7 | 719 | 0.0 | 0.279 | 0.00 |
| 1st Floor – Cafeteria | 71.6 | 62.2 | 0.7 | 937 | 0.0 | 0.349 | 0.00 |
| 1st Floor – C Wing Hall | 72.5 | 57.9 | 0.7 | 689 | 0.0 | 0.298 | 0.00 |
| 1st Floor – Class D-107 | 71.7 | 56.4 | 0.7 | 602 | 0.0 | 0.275 | 0.00 |
| 1st Floor – D Wing Hall | 71.0 | 56.9 | 0.7 | 584 | 0.0 | 0.265 | 0.00 |

| | | | ^ = | 555 | 0.0 | 0.000 | 0.00 |
|---|------|------|-----|------|-----|-------|------|
| 1st Floor – Auditorium | 69.5 | 56.5 | 0.7 | 555 | 0.0 | 0.266 | 0.00 |
| 2 nd Floor – Library | 73.4 | 56.7 | 0.7 | 1042 | 0.0 | 0.473 | 0.00 |
| 2 nd Floor – A Wing Hall | 73.9 | 57.5 | 1.0 | 1104 | 0.0 | 0.512 | 0.00 |
| 2 nd Floor – Class A-213 | 73.9 | 57.0 | 0.7 | 1082 | 0.0 | 0.534 | 0.00 |
| 2 nd Floor – A Wing Teachers Room | 75.1 | 56.9 | 0.7 | 888 | 0.0 | 0.480 | 0.00 |
| 2 nd Floor – Class A-202 | 73.6 | 55.4 | 0.7 | 860 | 0.0 | 0.488 | 0.00 |
| 2 nd Floor – E Wing Hall | 73.8 | 53.8 | 0.8 | 735 | 0.0 | 0.471 | 0.00 |
| 2 nd Floor – Office E-201 | 73.3 | 52.4 | 0.7 | 766 | 0.0 | 0.413 | 0.00 |
| 2 nd Floor – Class E-207 | 73.2 | 54.5 | 0.7 | 820 | 0.0 | 0.464 | 0.00 |
| 2 nd Floor – Class E-232 | 73.6 | 53.9 | 0.7 | 806 | 0.0 | 0.457 | 0.00 |
| 3 rd Floor – Class E-337 | 74.5 | 52.3 | 0.7 | 773 | 0.0 | 0.518 | 0.00 |
| 3 rd Floor – E Wing Hall | 74.5 | 52.6 | 0.7 | 828 | 0.0 | 0.503 | 0.00 |
| 3 rd Floor – Stairwell E Wing | 74.7 | 53.5 | 0.7 | 898 | 0.0 | 0.485 | 0.00 |
| 3 rd Floor – Class E-333 | 74.7 | 52.6 | 0.7 | 806 | 0.0 | 0.503 | 0.00 |
| 3 rd Floor – Class A-301 | 74.0 | 51.0 | 0.7 | 662 | 0.0 | 0.479 | 0.00 |
| 3 rd Floor – A Wing Hall | 71.6 | 53.1 | 0.7 | 839 | 0.0 | 0.519 | 0.00 |
| 3 rd Floor – Class A-323 | 70.7 | 52.6 | 0.7 | 800 | 0.0 | 0.535 | 0.00 |
| LL – E Wing Hall | 70.4 | 56.0 | 0.7 | 796 | 0.0 | 0.024 | 0.00 |
| LL – Stair E-ST2 | 70.6 | 56.2 | 0.7 | 797 | 0.0 | 0.530 | 0.00 |
| LL – Automotive Class | 70.4 | 55.4 | 0.7 | 737 | 0.0 | 0.076 | 0.00 |
| LL – A Wing Hall | 70.3 | 57.1 | 0.6 | 704 | 0.0 | 0.080 | 0.00 |
| LL – Class A-005 | 70.4 | 57.0 | 0.7 | 802 | 0.0 | 0.087 | 0.00 |
| LL – Class A-014 | 70.3 | 57.7 | 0.7 | 814 | 0.0 | 0.099 | 0.00 |
| LL – Stair C-ST1 | 71.5 | 56.9 | 0.7 | 796 | 0.0 | 0.100 | 0.00 |
| LL – A Wing Lobby Near Exit 23 | 70.9 | 56.3 | 0.7 | 812 | 0.0 | 0.120 | 0.00 |
| 1st Floor – E Wing Hall | 71.2 | 57.7 | 0.7 | 1033 | 0.0 | 0.192 | 0.00 |
| 1st Floor – Class E-104 | 71.9 | 55.4 | 0.7 | 816 | 0.0 | 0.173 | 0.00 |
| 1st Floor – Class E-133 | 72.0 | 54.5 | 0.7 | 815 | 0.0 | 0.237 | 0.00 |
| 1st Floor – Class E-105 | 71.8 | 55.5 | 0.7 | 825 | 0.0 | 0.200 | 0.00 |
| 1 st Floor – E Wing Common Area | 71.8 | 54.8 | 0.7 | 785 | 0.0 | 0.215 | 0.00 |
| 1st Floor – Class E-127 | 71.7 | 55.5 | 0.7 | 835 | 0.0 | 0.216 | 0.00 |
| 1st Floor – A Wing Hall | 71.4 | 56.6 | 0.7 | 802 | 0.0 | 0.213 | 0.00 |
| 1st Floor – Class A-160 | 70.7 | 54.9 | 0.7 | 727 | 0.0 | 0.209 | 0.00 |
| 1st Floor – Class A-158 | 70.3 | 53.5 | 0.7 | 773 | 0.0 | 0.212 | 0.00 |
| 1st Floor – Main Entrance Lobby | 71.5 | 53.2 | 0.7 | 865 | 0.0 | 0.206 | 0.00 |
| 1st Floor – Main Office | 72.0 | 52.5 | 0.7 | 760 | 0.0 | 0.216 | 0.00 |
| 1st Floor Pupil Services | 72.1 | 52.8 | 0.7 | 743 | 0.0 | 0.189 | 0.00 |

| 1st Floor – Stair E-ST1 | 72.3 | 53.2 | 0.7 | 679 | 0.0 | 0.186 | 0.00 |
|---|------|------|-----|------|-----|-------|------|
| 1st Floor – Career Center | 72.1 | 52.5 | 0.7 | 641 | 0.0 | 0.198 | 0.00 |
| 1st Floor – Class C-123 | 71.8 | 52.8 | 0.7 | 674 | 0.0 | 0.199 | 0.00 |
| LL – Weight Room | 70.0 | 56.0 | 0.8 | 630 | 0.0 | 0.203 | 0.00 |
| LL – Gym Lobby Near B | 69.4 | 53.0 | 0.8 | 616 | 0.0 | 0.198 | 0.00 |
| LL – Cardio Room | 69.6 | 64.5 | 0.7 | 1149 | 0.0 | 0.125 | 0.00 |
| LL – Gym | 69.6 | 54.1 | 0.6 | 652 | 0.0 | 0.208 | 0.00 |
| 1st Floor – Cafeteria | 71.1 | 62.5 | 0.7 | 1343 | 0.0 | 0.269 | 0.00 |
| 1st Floor – C Wing Hall | 71.9 | 54.4 | 0.7 | 709 | 0.0 | 0.258 | 0.00 |
| 1st Floor – Class D-102 | 70.7 | 51.5 | 0.7 | 715 | 0.0 | 0.222 | 0.00 |
| 1st Floor – D Wing Hall | 72.7 | 53.6 | 0.7 | 720 | 0.0 | 0.228 | 0.00 |
| 1st Floor – Auditorium | 70.9 | 55.0 | 0.7 | 815 | 0.0 | 0.210 | 0.00 |
| 2 nd Floor – Library | 72.5 | 55.0 | 0.7 | 976 | 0.0 | 0.350 | 0.00 |
| 2 nd Floor – A Wing Hall | 72.5 | 55.0 | 0.7 | 1003 | 0.0 | 0.376 | 0.00 |
| 2 nd Floor – Class A-213 | 72.6 | 55.5 | 0.7 | 976 | 0.0 | 0.314 | 0.00 |
| 2 nd Floor – A Wing Teachers Room | 73.3 | 54.5 | 0.7 | 930 | 0.0 | 0.353 | 0.00 |
| 2 nd Floor – Class A-202 | 72.7 | 55.9 | 0.7 | 1174 | 0.0 | 0.395 | 0.00 |
| 2 nd Floor – E Wing Hall | 72.9 | 53.1 | 0.7 | 901 | 0.0 | 0.370 | 0.00 |
| 2 nd Floor – Office E-201 | 72.3 | 49.7 | 0.7 | 700 | 0.0 | 0.317 | 0.00 |
| 2 nd Floor – Class E-207 | 72.2 | 51.2 | 0.7 | 768 | 0.0 | 0.331 | 0.00 |
| 2 nd Floor – Class E-332 | 73.2 | 51.1 | 0.8 | 738 | 0.0 | 0.330 | 0.00 |
| 3 rd Floor – Class E-331 | 73.1 | 54.5 | 0.7 | 998 | 0.0 | 0.423 | 0.00 |
| 3 rd Floor – E Wing Hall | 73.2 | 50.8 | 0.7 | 811 | 0.0 | 0.392 | 0.00 |

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|------------------------------------|-------|--------|----------|-----------------------|----------------------------|-----------|-----------------------|
| Outside | 49.9 | 80.2 | 0.0 | 572 | 0.0 | 0.0 | 0.0 |
| Classroom A106 | 70.0 | 57.8 | 1.0 | 748 | 0.0 | .101 | 0.0 |
| 1st Floor Lobby Area | 70.8 | 57.2 | 0.9 | 794 | 0.0 | .092 | 0.0 |
| A Wing Hallway | 71.3 | 57.3 | 1.2 | 1009 | 0.0 | 0.178 | 0.0 |
| Classroom E104 | 71.4 | 56.6 | 0.9 | 887 | 0.0 | 0.145 | 0.0 |
| Stairwell E-ST2 1 | 71.9 | 57.4 | 1.1 | 1054 | 0.0 | 0.214 | 0.0 |
| Classroom E121 | 72.4 | 57.0 | 0.8 | 1027 | 0.0 | 0.256 | 0.0 |
| E Wing Hallway | 72.9 | 55.8 | 1.2 | 962 | 0.0 | 0.273 | 0.0 |
| First Floor Exit 5 | 72.8 | 55.6 | 1.2 | 936 | 0.0 | 0.269 | 0.0 |
| Classroom E132 | 73.3 | 55.5 | 1.1 | 947 | 0.0 | .272 | 0.0 |
| Front Office | 72.5 | 55.4 | 1.2 | 862 | 0.0 | .268 | 0.0 |
| Pupil Services Room 115 | 73.3 | 54.9 | 1.1 | 915 | 0.0 | .302 | 0.0 |
| A Wing Hall, Outside Counseling | 73.3 | 54.2 | 1.2 | 936 | 0.0 | 0.300 | 0.0 |
| Cafeteria | 72.9 | 55.4 | 1.1 | 734 | 0.0 | 0.287 | 0.0 |
| D Wing Hall – Ticket Booth | 71.3 | 52.1 | 1.2 | 648 | 0.0 | 0.238 | 0.0 |
| Auditorium | 69.8 | 53.1 | 1.3 | 641 | 0.0 | 0.226 | 0.0 |
| D107 – Band | 69.9 | 57.5 | 0.8 | 637 | 0.0 | 0.191 | 0.0 |
| D Wing Hall – Drama Closet | 70.1 | 57.5 | 1.0 | 641 | 0.0 | 0.200 | 0.0 |
| Gymnasium | 70.7 | 56.6 | 1.0 | 619 | 0.0 | 0.206 | 0.0 |
| Gym Office | 70.9 | 56.7 | 1.1 | 592 | 0.0 | 0.201 | 0.0 |
| Gym Hallway | 70.5 | 56.0 | 1.3 | 651 | 0.0 | 0.242 | 0.0 |
| Weight Room | 69.2 | 58.1 | 1.1 | 641 | 0.0 | 0.218 | 0.0 |
| Classroom A160 | 71.6 | 57.3 | 0.9 | 846 | 0.0 | 0.313 | 0.0 |
| Auto Lab | 71.0 | 56.2 | 1.2 | 818 | 0.0 | 0.348 | 0.0 |
| Stair E-ST2 L | 71.4 | 58.0 | 1.2 | 872 | 0.0 | 0.322 | 0.0 |
| Classroom A005 | 74.2 | 56.4 | 0.9 | 940 | 0.0 | 0.341 | 0.0 |
| A Wing Lower-Level Hallway | 73.4 | 54.8 | 1.3 | 958 | 0.0 | 0.349 | 0.0 |
| Classroom A015 | 72.3 | 55.6 | 1.3 | 886 | 0.0 | 0.346 | 0.0 |
| Stair C-ST1 L | 72.5 | 56.2 | 1.2 | 1101 | 0.0 | 0.363 | 0.0 |
| Library | 73.8 | 56.0 | 1.3 | 1185 | 0.0 | 0.466 | 0.0 |
| A Wing Hallway Floor 2 | 73.9 | 57.5 | 1.2 | 1255 | 0.0 | 0.474 | 0.0 |
| Classroom A212 | 74.4 | 56.3 | 1.2 | 1153 | 0.0 | 0.493 | 0.0 |
| Classroom A206 | 74.2 | 55.1 | 1.3 | 1099 | 0.0 | 0.444 | 0.0 |

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|---|-------|--------|----------|-----------------------|----------------------------|-----------|-----------------------|
| A wing Hallway near Elevator 2 nd Floor | 74.5 | 55.7 | 1.2 | 949 | 0.0 | 0.414 | 0.0 |
| Room E212 | 74.1 | 53.3 | 1.2 | 780 | 0.0 | 0.395 | 0.0 |
| E Wing Hallway Floor 2 | 74.1 | 56.0 | 1.2 | 954 | 0.0 | 0.445 | 0.0 |
| Classroom E224 | 73.5 | 53.7 | 1.3 | 859 | 0.0 | 0.395 | 0.0 |
| Stair E-ST1 2 | 74.0 | 55.0 | 1.2 | 983 | 0.0 | 0.411 | 0.0 |
| Assistant Principals Office 3 rd Floor | 74.1 | 52.3 | 1.3 | 651 | 0.0 | 0.397 | 0.0 |
| Classroom E334 | 74.4 | 55.2 | 1.2 | 940 | 0.0 | 0.457 | 0.0 |
| Classroom E330 | 74.3 | 54.0 | 1.2 | 895 | 0.0 | 0.464 | 0.0 |
| A Wing Hallway 3rd Floor | 74.8 | 54.2 | 1.2 | 990 | 0.0 | 0.437 | 0.0 |
| Classroom A234 | 74.7 | 58.2 | 1.3 | 1270 | 0.0 | 0.566 | 0.0 |
| Outside | 51.1 | 80.6 | 0.0 | 581 | 0.0 | 0.0 | 0.0 |
| Classroom A106 | 71.4 | 57.8 | 0.7 | 881 | 0.0 | 0.133 | 0.0 |
| 1st Floor Lobby Area | 72.0 | 57.3 | 0.7 | 876 | 0.0 | 0.135 | 0.0 |
| A Wing Hallway | 72.5 | 53.0 | 0.9 | 615 | 0.0 | 0.131 | 0.0 |
| Classroom E104 | 72.4 | 52.2 | 0.9 | 894 | 0.0 | 0.333 | 0.0 |
| Stairwell E-ST2 1 | 72.8 | 54.4 | 0.8 | 1030 | 0.0 | 0.326 | 0.0 |
| Classroom E121 | 72.6 | 53.5 | 1.2 | 1056 | 0.0 | 0.355 | 0.0 |
| E Wing Hallway | 72.5 | 52.7 | 0.9 | 937 | 0.0 | 0.344 | 0.0 |
| First Floor Exit 5 | 72.4 | 52.2 | 0.8 | 835 | 0.0 | 0.357 | 0.0 |
| Classroom E132 | 72.6 | 51.4 | 8.0 | 753 | 0.0 | 0.349 | 0.0 |
| Front Office | 72.5 | 55.6 | 0.7 | 760 | 0.0 | 0.148 | 0.0 |
| Pupil Services Room 115 | 72.7 | 54.0 | 1.1 | 648 | 0.0 | 0.131 | 0.0 |
| A Wing Hall, Outside Counseling | 72.0 | 57.3 | 0.7 | 955 | 0.0 | 0.244 | 0.0 |
| Cafeteria | 72.9 | 63.5 | 1.3 | 1566 | 0.0 | 0.267 | 0.0 |
| D Wing Hall – Ticket Booth | 72.9 | 52.4 | 1.1 | 680 | 0.0 | 0.169 | 0.0 |
| Auditorium | 71.6 | 50.5 | 0.9 | 578 | 0.0 | 0.173 | 0.0 |
| D107 – Band | 70.6 | 53.8 | 0.8 | 612 | 0.0 | 0.176 | 0.0 |
| D Wing Hall – Drama Closet | 70.6 | 54.0 | 0.9 | 621 | 0.0 | 0.171 | 0.0 |
| Gymnasium | 71.3 | 52.5 | 1.0 | 590 | 0.0 | 0.214 | 0.0 |
| Gym Office | 71.7 | 52.2 | 0.7 | 627 | 0.0 | 0.216 | 0.0 |
| Gym Hallway | 71.1 | 52.6 | 0.8 | 637 | 0.0 | 0.207 | 0.0 |
| Weight Room | 69.2 | 54.1 | 0.7 | 556 | 0.0 | 0.203 | 0.0 |
| Classroom A160 | 71.5 | 53.2 | 1.1 | 880 | 0.0 | 0.344 | 0.0 |
| Auto Lab | 72.2 | 51.6 | 1.1 | 703 | 0.0 | 0.345 | 0.0 |
| Stair E-ST2 L | 73.3 | 51.1 | 0.9 | 904 | 0.0 | 0.414 | 0.0 |

| Location | Temp. | RH (%) | CO (ppm) | CO ₂ (ppm) | CH ₂ O (ppm) | VOC (ppm) | Dust Conc. (mg/m³) |
|---|-------|--------|----------|-----------------------|----------------------------|-----------|-----------------------|
| Classroom A005 | 71.1 | 52.7 | 0.7 | 840 | 0.0 | 0.358 | 0.0 |
| A Wing Lower-Level Hall | 70.8 | 54.7 | 0.7 | 1033 | 0.0 | 0.354 | 0.0 |
| Classroom A015 | 71.4 | 54.3 | 0.7 | 942 | 0.0 | 0.370 | 0.0 |
| Stair C-ST1 L | 72.6 | 53.1 | 0.7 | 795 | 0.0 | 0.350 | 0.0 |
| Library | 72.6 | 52.1 | 0.9 | 870 | 0.0 | 0.434 | 0.0 |
| A Wing Hallway Floor 2 | 73.7 | 53.3 | 0.8 | 1168 | 0.0 | 0.455 | 0.0 |
| Classroom A212 | 73.1 | 55.0 | 1.1 | 1201 | 0.0 | 0.424 | 0.0 |
| Classroom A206 | 73.5 | 52.8 | 1.1 | 1109 | 0.0 | 0.453 | 0.0 |
| A wing Hallway near Elevator 2 nd Floor | 73.3 | 49.2 | 0.8 | 851 | 0.0 | 0.437 | 0.0 |
| Room E212 | 72.2 | 49.6 | 1.0 | 805 | 0.0 | 0.543 | 0.0 |
| E Wing Hallway Floor 2 | 72.0 | 49.3 | 0.9 | 883 | 0.0 | 0.451 | 0.0 |
| Classroom E224 | 72.5 | 49.6 | 0.9 | 807 | 0.0 | 0.432 | 0.0 |
| Stair E-ST1 2 | 73.1 | 49.7 | 0.8 | 992 | 0.0 | 0.422 | 0.0 |
| Assistant Principals Office 3 rd Floor | 73.1 | 49.1 | 0.7 | 795 | 0.0 | 0.443 | 0.0 |
| Classroom E334 | 71.6 | 47.0 | 0.8 | 672 | 0.0 | 0.436 | 0.0 |
| Classroom E330 | 72.1 | 46.9 | 0.7 | 602 | 0.0 | 0.404 | 0.0 |
| A Wing Hallway 3 rd Floor | 73.3 | 51.1 | 0.9 | 944 | 0.0 | 0.434 | 0.0 |
| Classroom A234 | 72.8 | 50.7 | 1.1 | 807 | 0.0 | 0.454 | 0.0 |

III. PHOTOGRAPHS












Figure 1. A1 Exterior Baseline (Top Left), A2 Automotive Classroom (Top Right), A3 Wing Exit Near Paring Lot (Bottom Left) and A4 E Wing Common Area (Bottom Right).










Figure 2. A5 Main Entrance Lobby (Top Left), A6 Cafeteria (Top Right), A7 Library (Bottom Left), A8 9th Grade Deans Office (Bottom Right)











Figure 3. A9 Room E347 (Top Left) and A10 Hallway Near Stair Well 3rd Floor (Top Right), A11 Exterior Baseline (Bottom Left), and A12 LL. E Wing Hall Lobby Area (Bottom Right)










Figure 4. A13 LL. Classroom A006 (Top Left), and A14 First Floor E132 (Top Right). A15 1st Floor Main Office (Bottom Left), A17 2nd Floor Teachers Lounge.










Figure 5. A18 Class E204 (Top Left), A19 E336 (Top Right), and A20 Class A303 (Bottom Left)











Figure 6. A21 Outdoor Baseline (Top Left), A22 Class A014 (Top Left), A23 Floor Class E133, A24 Pupil Services










Figure 7. A25 Weight Room (Top Left), A26 Class D107 (Top Left), A27 Stair CST1 (Bottom Left), and Office E201 (Bottom Right).






Figure 8. A29 Class E337 (Left) and A30 Class A301 (Right).










Figure 9. A31 Classroom A106 (Top Left), A32 E Wing Stair EST2 (Top Right), A33 Cafeteria (Bottom Left), and A34 Gym Office (Bottom Right)











Figure 10. A35 Preschool A005 (Top Left), A36 Room E212 (Top Right), A38 3rd Floor Assistant Principals (Bottom Left), and A-40 Exterior Baseline (Bottom Right).










Figure 11. A41 LL. Men's Bathroom Near Exit 10 (Top Left), A42 Cafeteria/Kitchen (Top Right), A43 Classroom across from C012 (Bottom Right), A44 Ticket Booth Office (Bottom Left).






Figure 12. A47 Classroom A226 (Left) and A49 Elevator (Right)




Figure 13. Automotive Classroom and location of clearance sample A1. Figure from re-test taken on November 7, 2023.